

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Inspection Report

Permit Number:	C0070001		
Inspection Type:	PARTIAL		
Inspection Date:	Monday, January 03, 2011		
Start Date/Time:	1/3/2011 1:00:00 PM		
End Date/Time:	1/3/2011 1:30:00 PM		
Last Inspection:	Wednesday, December 14, 2011		

Inspector: Priscilla Burton,

Weather: sun, 20F

InspectionID Report Number: 2610

Accepted by: jhelfric

1/26/2011

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

Permitee: LODESTAR ENERGY INC

Operator:

Site: WHITE OAK MINE

Address: ,

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Mineral Ownership			
	Mina	 	h:

Types of Operations

Reprocessing

3,906.00	Total Permitted		
151.10	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Current Acreages

✓ Federal
✓ Underground
✓ State
✓ Surface
✓ County
✓ Loadout
✓ Fee
Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Other

Both loadout and mine site were inaccessible from Hwy 96.

Inspector's Signature

Inspector ID Number: 37

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Priscilla Burton,



Date

Thursday, January 06, 2011

Permit Number: C0070001 Inspection Type: PARTIAL

Inspection Date: Monday, January 03, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues	V		V	
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.2	Roads: Construction, Maintenance, Surfacing	✓		~	
16.k	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070001 Inspection Type: PARTIAL

Inspection Date: Monday, January 03, 2011

Page 3 of 3

9. Protection of Fish, Wildlife and Related Environmental Issues

Confluence of Whiskey Creek and Eccles Creek is not turbid. At loadout, culvert C-14-42 is sending steady flow to Mud Creek (see Dwg R645-301-527 Sheet 2).

16.a Roads: Construction, Maintenance, Surfacing

Roads not accessible from Hwy 96 at either mine site or loadout.